



Total Quality. Assured.

545 E Algonquin Road, Suite H  
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667  
[intertek.com](http://intertek.com)

Published: January 21, 2020  
Revised:

Public Notice ID: 2020-3  
Page 1 of 2

## Counterfeit Intertek Certification Certificate / Certificat de certification Intertek de contrefaçon Dongyi Coffee Roaster

Notification Type:	Counterfeiting / Contrefaçon
Certification Type:	ETL Listed - US and Canada

### Notification

Intertek notifies consumers, retailers and distributors that we have been made aware of counterfeit Intertek certificates in the marketplace as identified below claiming products are Intertek Certified. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été informés de la contrefaçon de certificats Intertek sur le marché comme indiqué ci-dessous les produits de revendication sont certifiés Intertek.

### Company Identification

Nanyang Dongyi Machinery Equipment Co., Ltd.

### Product Identification

Counterfeit document Authorization to Mark, No date documented, Coffee Roasting Machine, models ☐  
DY-1, DY-2, DY-3, DY-6, DY-12, DY-15, DY-20, DY-20, DY-30, DY-60, DY-120, DY-200, DY-300, BY-1, BY-2, BY-3, BY-6 control number 5223466.

### Hazard Involved

Unknown

### What To Do

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.



Total Quality. Assured.

Published: January 21, 2020  
Revised:

Photos and Images

COUNTERFEIT

545 E Algonquin Road, Suite H  
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667  
intertek.com

Public Notice ID: 2020-3  
Page 2 of 2

COUNTERFEIT



### AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple issue model(s) identified on the correlation page of the Listing Report.

This document is the property of Intertek Testing Services and is not transferable. The Certification Mark(s) may be applied only at the location of the Party Authorized To Apply Mark.

**Applicant:** Nanyang Dongyi Machinery Equipment Co., Ltd  
**Address:** No.68 Xinchen Road, Gaoxin District, Nanyang City, Henan Province  
**Country:** China

**Manufacturer:** Nanyang Dongyi Machinery Equipment Co., Ltd  
**Address:** No.68 Xinchen Road, Gaoxin District, Nanyang City, Henan Province  
**Country:** China

**Party Authorized To Apply Mark:** Same as Manufacturer  
**Report Issuing Office:** Intertek Testing Services HK Limited

**Control Number:** 5223466

Authorized by:   
for the Party Authorized To Apply Mark




This document supersedes all previous Authorizations to Mark for the noted Report Number. This authorization is for the exclusive use of the Applicant's Client and is provided to the Client upon request. Intertek and its Client Intertek's responsibility and liability are limited to the extent and within the scope of the agreement. Intertek does not warrant, either express or implied, that the Client or any third party will not be liable for any loss, expense or damage incurred by the use of the Certification Mark(s). Intertek does not warrant, either express or implied, that the Client or any third party will not be liable for any loss, expense or damage incurred by the use of the Certification Mark(s) in violation of the conditions set out in the agreement and in the Authorization to Mark. Any further use of the Certification Mark(s) for the sale or all other purposes of the noted material, product or service must first be approved in writing by Intertek. Intertek Factory Assessments and Follow-Up Services are for the purpose of ensuring appropriate usage of the Certification Mark(s) accordance with the agreement. They are not for the purpose of production control and do not release the Client of their obligations in this regard.

Intertek Testing Service HK Ltd.  
2/F, Garment Centre, 576 Castle Peak Rd, Cheung Sha Wan, Hong Kong  
Telephone: +852 2173 8888

<b>Standard(s):</b>	UL 197: Issue:2010/03/17 Ed:10 Rev:2011/06/24 UL Standard for Saftey Commercial Electric Cooking Appliances UL 703: Issue:2012/01/31 UL Standard for Motor-Operated Commercial Food Preparing Machines CSA C22.2 No. 109: Issue:2017/05/01 Commercial Cooking Appliances General Instruction No 1-3 (R2009)
<b>Product:</b>	Coffee Roasting Machine
<b>Brand Name:</b>	Dongyi Coffee Roaster
<b>Model(s):</b>	DY-1, DY-2, DY-3, DY-6, DY-12, DY-15, DY-20, DY-20, DY-30, DY-60, DY-120, DY-200, DY-300 BY-1, BY-2, BY-3, BY-6

Gas Fitting Compliance

WORK DONE BY:   
DATE: 10/09/2019

DESCRIPTION OF GAS FITTING WORK DONE:  
replaced burner (LPG) for natural gas burner, old burner stays with machine

RISK CLASSIFICATION: low

GAS TYPE: natural gas

THE WORK HAS BEEN DONE ACCORDANCE TO THE MANUFACTURER SPECIFICATIONS: YES

  
Nanyang Dongyi Machinery Equipment Co., Ltd  
No. 68 Xinchen Rd, Gaoxin District, Nanyang City, Henan Province - China